

From: ["Stuesse, Gregory L." <stuessegl@cdmsmith.com>](mailto:stuessegl@cdmsmith.com)
To: ["Sheldrake, Sean" <sheldrake.sean@epa.gov>](mailto:sheldrake.sean@epa.gov)
["Zhen, Davis" <Zhen.Davis@epa.gov>](mailto:Zhen.Davis@epa.gov)
CC: ["Scott Coffey" <coffeyse@cdmsmith.com>](mailto:coffeyse@cdmsmith.com)
["Irby-Smith, Karen" <lrbySmithKE@cdmsmith.com>](mailto:lrbySmithKE@cdmsmith.com)
["Miner, Libby" <minerl@cdmsmith.com>](mailto:minerl@cdmsmith.com)
Date: 5/24/2018 6:51:02 PM
Subject: Surface Sediment Photos from the Tieton 5/24 PM
Attachments: [SG-337_2018-05-24_\(1\).JPG](#)
[SG-337_2018-05-24_\(2\).JPG](#)
[SG-337_2018-05-24_\(3\).JPG](#)

Sean and Davis,

Attached are photos from Karen on the Tieton that is sampling today at Stratified Random Sample locations. Photos were taken at SG-B337 located near RM 10 to 10.5W in front of Sause Bros as shown in photo SG-337_2018_06_24_(1) taken at 13:36 today. The photos show the sediments within the grab sampler and samples from the three grabs prior to mixing.

A 3-point composite sample was collected in three grabs with recoveries greater than 25 cm. The sample generally consists of dark gray, very soft to medium stiff, very fine sandy silt with scattered fine organics.

Sampling at SG-B333 this afternoon, which is also located near RM 10 to 10.5 W in front of Sause Bros. The crew is getting good recovery with similar sediment composition with slightly less sand.

Thanks, Greg

Greg Stuesse, PE, LG | Senior Project Manager | CDM Smith

14432 SE Eastgate Way, Suite 100 | Bellevue, WA 98007

Main: 425.519.8300 | Direct: 425.519.8358 | Cell: 206-715-6752

stuessegl@cdmsmith.com | <mailto:stuessegl@cdmsmith.com%7C> www.cdmsmith.com <<http://www.cdmsmith.com>>